

**Niagara Falls Boulevard
Niagara County, New York
2019 Removal Action Daily Report**

Date: Thursday, November 14, 2019

Personnel On-Site:

EPA OSC – Peter Lisichenko

START V – Mallory Neldner & Sean Quinn

ERRS Contractor: Guardian Environmental Services (GES)

Weather: Cloudy, 0% snow showers, Lo: 18°F, High: 29°F, Winds: 5-9 mph, due N, 87% humidity.

Health and Safety: Safety topics included: being aware of slips, trips, and falls, site traffic and heavy equipment awareness, cold stress, using proper personal protective equipment (PPE), high winds, and radiation hazards.

Activities Completed:

1. ERRS accepted deliveries of backfill. Material is being staged in EA 12 for use in the building supply center as well as for final backfill for EA 12.
2. ERRS conducts snow/ice removal from heavy equipment and walkways.
3. ERRS mixed the disposal pile in preparation for loading trucks.
4. HERC was on site to remove 3 heaters.
5. START V set up and checked air monitoring equipment throughout the work day.
6. START V conducted calibration check of the Ludlum 2241-2
7. ERRS continued organizing windows and removing the wall at ST-4.
8. START V conducted soil analyses using the HPGe.
9. At the end of the work day, START V uploaded field data to the EPA internet SharePoint site designated for the Site.

Planned Activities for November 15, 2019:

1. ERRS will continue to receive backfill, storing it in EA 12 for future distribution.
2. ERRS will begin excavation activities at ST-4.
3. START V will continue to conduct soil sampling analysis.

**Niagara Falls Boulevard
Niagara County, New York
2019 Removal Action Daily Report**

Soil Excavation & Backfill Data:

Soil Volume Excavated Today (In Cubic Yards)	0
Cumulative Soil Volume Excavated (In Cubic Yards) ¹	3,418.5
Total Number of Disposal Trucks Today	0
Total Number of Disposal Trucks to Date	0
Number of Backfill Trucks Today	7
Number of Backfill Trucks to Date	227
Backfill Received Today (In Tons)	334.6
Cumulative Backfill Volume to Date (In Tons)	8133.01

¹ Corrected value based on ERRS reported totals for each area.

**Niagara Falls Boulevard
Niagara County, New York
2019 Removal Action Daily Report**

Site Photographs



View of ERRs de-icing equipment.



View ERRs crew breaking concrete at ST-4.